Larrawa station—producer demonstration site

Photo story of works completed November 2011



Photo 1. Larrawa station regeneration monitoring site no.4 (pre works).



Photo 2. Ripping before bank construction with 16G grader.



Photo 3. Soil crust post ripping.



Photo 4. Collecting markers between rip lines before building bank. The non-ripped area between rip lines will form the bank base.



Photo 5. Taking first blade of soil to form bank, starting on outside of pond.



Photo 6. Taking second blade of soil (rolling onto existing bank) on inside of pond.



Photo 7. Completed bank. The domed top will allow rainfall to flow away, minimising pooling on bank top.



Photo 8. Casting forage sorghum on inside of bank to ensure germinable seed is present.



Photo 9. Larrawa station regeneration monitoring site no.4 (post works).



Photo 10. Aerial shot of regeneration area.







